



AUBURN

UNIVERSITY

2011 ANNUAL FIRE SAFETY REPORT

A document produced by Auburn University
In compliance with the requirements of the
Higher Education Opportunity Act

**Auburn University
Risk Management and Safety
316 Leach Science Center
Auburn, Alabama 36849
334.844.4870**

MESSAGE FROM THE FIRE SAFETY PROGRAM MANAGER

On August 14, 2008 the Higher Education Opportunity Act (HEOA) was signed into law. Under HEOA, institutions that maintain on-campus student housing are required to publish an annual fire safety report that discloses campus fire safety practices and standards of the institution to the U.S. Department of Education, the campus community and to the general public. Components of this law are intended to help ensure America's college students, their parents and the public have uniform, valid and easy to understand information regarding an institution's fire safety practices and standards.

I'm pleased to provide the 2011 Annual Fire Safety Report. This report meets all HEOA requirements and will provide you with information on the services that were performed to ensure the safety and welfare of our students, faculty, staff, and visitors and minimize the disruption of university operations.

Auburn University's Risk Management and Safety, Fire Safety Program Staff are responsible for performing: fire safety education; code research and consultation; inspection, testing and maintenance of all pre-engineered restaurant fire extinguishment systems, special hazard fire extinguishment systems, water-based fire protection systems, and portable fire extinguishers; records management; fire and life safety plan reviews of new construction and renovation projects; inspection of new construction and new fire protection systems for code compliance and operational integrity; plus fire and life safety inspections of existing campus buildings; and we serve as a liaison to the City of Auburn Fire Department. Our staff is committed to providing exceptional fire safety services to protect our campus which consists of 25,469 students, 1,177 faculty members and 3,433 full-time staff members. Additionally, there are 427 buildings that house students, athletic events, research, laboratories, classrooms, livestock and administrative offices. These facilities are spread over 1,841 acres of land and have a cumulative property value of \$3 billion.

To accomplish these services, the Fire Safety Staff maintains collaborative working relationships with other University departments and outside agencies to include: Faculty, Staff, Students, Facilities Division, Housing and Residential Life, Office of Greek Life, Athletics, University Public Safety and Security, the City of Auburn Public Safety Department (Fire Division, Inspections and Codes Enforcement Division, and the Police Division), State Fire Marshal's Office, State Building Commission, Contracted Architects, Engineers, Construction Project Managers, and Building/Fire Protection Contractors. This collaboration ensures maximum efficiency, fiscal responsibility and success in these areas of responsibility. We will continue to work diligently to meet the challenges and goal of providing a fire safe campus. I encourage you to partner with us in keeping Auburn University Fire Safe.

According to The Center for Campus Fire Safety from January 2000 to present, 77 fatal fires have been documented that occurred on a college campus, in Greek housing or in off-campus housing within 3-miles of campus, claiming a total of 109 victims.

I'm pleased to report there were no fire fatalities, no fire related injuries, and no loss of revenue on the campus of Auburn University during 2011; however, we did have one non-residential fire (Hargis Hall) with property damage that totaled \$250,000.

If you have any questions about campus fire safety or this report, please don't hesitate to contact me at 334.844.4870 or email me at harrik7@auburn.edu.

Kenneth D. Harrison

MISSION STATEMENT

To ensure the safety and welfare of University students, faculty, staff and visitors, protect the University's infrastructure, and minimize disruption of academic programs through fire prevention and life safety code efforts.

PROGRAM STAFF

Kenneth D. Harrison, Fire Safety Program Manager
MaryAnn MacKenzie, Fire & Life Safety Specialist
Patricia Davis, Fire & Life Safety Technician

2011 FIRE STATISTICS FOR ON-CAMPUS STUDENT HOUSING

Item	Location	Fire Cause	Number of Injuries	Number of Deaths	Property Damage Value
1	CDV Building-A	No Fire	0	0	\$0
2	CDV Building-B	No Fire	0	0	\$0
3	CDV Building-C	No Fire	0	0	\$0
4	CDV Building-D	No Fire	0	0	\$0
5	CDV Building-E	No Fire	0	0	\$0
6	CDV Building-F	No Fire	0	0	\$0
7	Dorm 1-Harper	No Fire	0	0	\$0
8	Dorm 2-Broun	Unintentional	0	0	\$0
9	Dorm 3-Little	No Fire	0	0	\$0
10	Dorm 4-Teague	No Fire	0	0	\$0
11	Dorm 5-Dowdell	No Fire	0	0	\$0
12	Dorm 6-Glenn	No Fire	0	0	\$0
13	Dorm 7-Lane	No Fire	0	0	\$0
14	Dorm 8-Lupton	No Fire	0	0	\$0
15	Dorm 9-Keller	No Fire	0	0	\$0
16	Dorm 10-Owen	Unintentional	0	0	\$0
17	Dorm A-Hollifield	No Fire	0	0	\$0
18	Dorm B-Duncan	No Fire	0	0	\$0
19	Dorm C-Toomer	No Fire	0	0	\$0
20	Dorm D-Dobbs	No Fire	0	0	\$0
21	Dorm E-Dunn	No Fire	0	0	\$0
22	Dorm F-Graves	No Fire	0	0	\$0
23	Dorm G-Dowell	No Fire	0	0	\$0
24	Dorm H-Knapp	No Fire	0	0	\$0
25	Dorm J-Boyd	No Fire	0	0	\$0
26	Dorm K-Sasnett	No Fire	0	0	\$0
27	Dorm L-Leischuck	No Fire	0	0	\$0

Item	Location	Fire Cause	Number of Injuries	Number of Deaths	Property Damage Value
28	Dorm M	No Fire	0	0	\$0
29	Village - Aubie	No Fire	0	0	\$0
30	Village - Eagle	No Fire	0	0	\$0
31	Village - Magnolia	No Fire	0	0	\$0
32	Village - Oak	No Fire	0	0	\$0
33	Village - Plainsman	No Fire	0	0	\$0
34	Village - Talon	No Fire	0	0	\$0
35	Village - Tiger	No Fire	0	0	\$0
36	Village - Willow	No Fire	0	0	\$0
37	Sewell Hall	No Fire	0	0	\$0
38	Alpha Gamma Rho	No Fire	0	0	\$0
39	Alpha Psi	No Fire	0	0	\$0
40	Beta Theta Pi	No Fire	0	0	\$0
41	Delta Chi	No Fire	0	0	\$0
42	Delta Sigma Phi	No Fire	0	0	\$0
43	Farm House Fraternity	No Fire	0	0	\$0
44	Kappa Alpha Order	No Fire	0	0	\$0
45	Phi Delta Theta	No Fire	0	0	\$0
46	Phi Kappa Tau	No Fire	0	0	\$0
47	Pi Kappa Phi	No Fire	0	0	\$0
48	Sigma Chi	Unintentional	0	0	\$0
49	Sigma Nu	No Fire	0	0	\$0
50	Sigma Phi Epsilon	No Fire	0	0	\$0
51	Sigma Pi	No Fire	0	0	\$0
52	Tau Kappa Epsilon	No Fire	0	0	\$0
53	Theta Chi	Unintentional	0	0	\$0
54	Theta Xi	No Fire	0	0	\$0
	Total Fires	4 Unintentional Fires	0	0	\$0

DESCRIPTION OF ON-CAMPUS HOUSING AND FIRE SAFETY SYSTEMS

HILL DORMS

The Hill consists of twelve dormitory buildings with a total occupant capacity of 1,482. There are 716 double occupancy rooms and 50 single occupancy rooms.

Hollifield Residence Hall (Dorm A), 285 West Samford Avenue

Built in 1962 and renovated in 1988, Dorm A is a three-story building with a basement. The building contains 29,680 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Duncan Residence Hall (Dorm B), 295 West Samford Avenue

Built in 1962 and renovated in 1988, Dorm B is a three-story building with a basement. The building contains 27,744 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Toomer Residence Hall (Dorm C), 437 Duncan Drive

Built in 1962 and renovated in 1988, Dorm C is a three-story building with a basement. The building contains 29,656 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Dobbs Residence Hall (Dorm D), 345 West Samford Avenue

Built in 1965 and renovated in 1988, Dorm D is a three-story building with a basement. The building contains 27,676 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Dunn Residence Hall (Dorm E), 435 Duncan Drive

Built in 1965 and renovated in 1989, Dorm E is a three-story building with a basement. The building contains 27,676 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Graves Residence Hall (Dorm F), 439 Duncan Drive

Built in 1965 and renovated in 1989, Dorm F is a three-story building with a basement. The building contains 27,687 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Dowell Residence Hall (Dorm G), 320 PO Davis Drive

Built in 1965 and renovated in 1989, Dorm G is a three-story building with a basement. The building contains 31,445 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Knapp Residence Hall (Dorm H), 302 PO Davis Drive

Built in 1966 and renovated in 1989, Dorm H is a three-story building with a basement. The building contains 31,434 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Boyd Residence Hall (Dorm J), 280 PO Davis Drive

Built in 1967 and renovated in 1990, Dorm J is a six-story building with a basement. The building contains 59,917 square feet and can house 212 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 2-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.
- An emergency generator is provided and supplies back-up power for all fire and life safety systems (i.e. fire pump, fire alarm system, emergency lights/exit signs).

Sasnett Residence Hall (Dorm K), 350 PO Davis Drive

Built in 1967 and renovated in 1990, Dorm K is a six-story building with a basement. The building contains 60,898 square feet and can house 212 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 2-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.
- An emergency generator is provided and supplies back-up power for all fire and life safety systems (i.e. fire pump, fire alarm system, emergency lights/exit signs).

Leischuck Residence Hall (Dorm L), 501 Duncan Drive

Built in 1994, Dorm L is a four-story building. The building contains 31,156 square feet and can house 101 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with zoned smoke detectors that are monitored by a zoned fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Residence Hall M (Dorm M), 282 PO Davis Drive

Built in 1994, Dorm M is a four-story building. The building contains 31,156 square feet and can house 101 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with zoned smoke detectors that are monitored by a zoned fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

QUAD DORMS

The Quad consists of ten dormitory buildings with a total occupant capacity of 967. There are 463 double occupancy rooms and 41 single occupancy rooms.

Harper Residence Hall (Dorm 1), 226 Mell Street

Built in 1938 and renovated in 1994, Dorm 1 is a three-story building with a basement. The building contains 20,868 square feet and can house 78 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.

- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Broun Residence Hall (Dorm 2), 246 Mell Street

Built in 1938 and renovated in 1994, Dorm 2 is a three-story building with a basement. The building contains 23,316 square feet and can house 101 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Little Residence Hall (Dorm 3), 304 Quad Drive

Built in 1938 and renovated in 1996, Dorm 3 is a three-story building with a basement. The building contains 26,734 square feet and can house 90 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored in a central location 24/7.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Teague Residence Hall (Dorm 4), 302 Quad Drive

Built in 1938 and renovated in 1996, Dorm 4 is a three-story building with a basement. The building contains 23,370 square feet and can house 90 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored in a central location 24/7.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.

- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Dowdell Residence Hall (Dorm 5), 266 Mell Street

Built in 1957 and renovated in 1999, Dorm 5 is a three-story building with a basement. The building contains 23,576 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Glenn Residence Hall (Dorm 6), 262 Roosevelt Drive

Built in 1957 and renovated in 1999, Dorm 6 is a three-story building with a basement. The building contains 23,552 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Lane Residence Hall (Dorm 7), 301 Quad Drive

Built in 1957 and renovated in 1997, Dorm 7 is a three-story building with a basement. The building contains 21,868 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Lupton Residence Hall (Dorm 8), 300 Roosevelt Drive

Built in 1957 and renovated in 1997, Dorm 8 is a three-story building with a basement. The building contains 21,868 square feet and can house 88 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Keller Residence Hall (Dorm 9), 329 Quad Drive

Built in 1957 and renovated in 1998, Dorm 9 is a three-story building with a basement. The building contains 21,868 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Owen Residence Hall (Dorm 10), 330 Roosevelt Drive

Built in 1957 and renovated in 1998, Dorm 10 is a three-story building with a basement. The building contains 23,085 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

All exit corridors and stairwells have a minimum of 1-hour fire rating.

- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler and standpipe system is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

THE VILLAGE DORMS

The Village consists of eight dormitory buildings with a total occupant capacity of 1,666. Buildings share a fire pump.

Magnolia Residence Hall, 201-E Wire Road

Built in 2009, Magnolia Hall is a four-story building with two, three and four bedroom suites. The building contains 105,322 square feet, and can house 233 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors, stairwells and assembly areas.

- All suites are equipped with addressable smoke detectors in each bedroom and the common living areas within each suit. All smoke detection devices are monitored by the building fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Oak Residence Hall, 201-F Wire Road

Built in 2009, Oak Hall is a four-story building with two, three and four bedroom suites. The building contains 108,104 square feet and can house 246 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors, stairwells and assembly areas.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Willow Residence Hall, 201-D Wire Road

Built in 2009, Willow Hall is a four-story building with two, three and four bedroom suites. The building contains 108,104 square feet and can house 246 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Aubie Residence Hall, 201-H Wire Road

Built in 2009, Aubie Hall is a four-story building with two, three and four bedroom suites. The building contains 107,755 square feet and can house 309 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire Evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Eagle Residence Hall, 201-G Wire Road

Built in 2009, Eagle Hall is a four-story building with two, three and four bedroom suites. The building contains 58,108 square feet and can house 153 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Tiger Residence Hall, 201-C Wire Road

Built in 2009, Tiger Hall is a four-story building with two, three and four bedroom suites. The building contains 58,108 square feet and can house 153 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Talon Residence Hall, 201-A Wire Road

Built in 2009, Tiger Hall is a four-story building with two, three and four bedroom suites. The building contains 60,439 square feet and can house 163 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

Plainsman Residence Hall, 201-B Wire Road

Built in 2009, Plainsman Hall is a four-story building with two, three and four bedroom suites. The building contains 60,439 square feet and can house 163 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- An automatic sprinkler system, standpipe system and fire pump is provided.

- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

CAROLINE DRAUGHON VILLAGE APARTMENTS

Caroline Draughon Village (CDV) consists of six three- story residential apartment buildings. The six buildings total 120,468 square feet and can house up to 552 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

CDV Apartment Building A, 731 Extension Drive

Built in 1980, CDV Apartment Building A is a three- story building with 17,765 square feet consisting of 21 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

CDV Apartment Building B, 721 Extension Drive

Built in 1980, CDV Apartment Building B is a three- story building with 21,533 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

CDV Apartment Building C, 280 Wire Road

Built in 1980, CDV Apartment Building C is a three- story building with 20,334 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

CDV Apartment Building D, 290 Wire Road

Built in 1980, CDV Apartment Building D is a three- story building with 21,533 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

CDV Apartment Building E, 751 Extension Drive

Built in 1980, CDV Apartment Building E is a three- story building with 20,339 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

CDV Apartment Building F, 741 Extension Drive

Built in 1980, CDV Apartment Building F is a three-story building with 18,959 square feet consisting of 21 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Built in 1979, CDV Apartment Building F is a two- story building consisting of 24 apartment units. Each unit has two bedrooms a can sleep four students. The building is a concrete building with a brick veneer finish. Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

SEWELL HALL DORM, 391 South Donahue Drive

Built in 1962, Sewell Hall Dorm is a three-story building with 24,689 square feet consisting of bedroom 72 units. The building is a concrete building with brick veneer.

- All bedrooms are equipped with battery operated smoke alarms and a portable fire extinguisher.
- Each unit opens onto an exterior corridor.

TABLE OF AUBURN UNIVERSITY ON-CAMPUS HOUSING FIRE SAFETY SYSTEMS

Building	Fire Alarm system	Dry Sprinkler	Wet Sprinkler	Fire Pump	Wet Standpipe	Smoke Detection	Fire Extinguishers	Range-Hood Fire Systems	Number of Fire Drills
Harper Hall (Dorm 1)	X	X	X		X	X	X		2
Broun Hall (Dorm 2)	X	X	X		X	X	X		2
Little Hall (Dorm 3)	X	X	X		X	X	X		2
Teague Hall (Dorm 4)	X	X	X		X	X	X		2
Dowdell Hall (Dorm 5)	X	X	X		X	X	X		2
Glenn Hall (Dorm 6)	X	X	X		X	X	X		2
Lane Hall (Dorm 7)	X	X	X		X	X	X		2
Lupton Hall (Dorm 8)	X	X	X		X	X	X		2
Keller Hall (Dorm 9)	X	X	X		X	X	X		2
Owen Hall (Dorm 10)	X	X	X		X	X	X		2
Boyd Hall (Dorm J)	X	X	X	X	X	X	X		2
Sasnett Hall (Dorm K)	X	X	X	X	X	X	X		2
Leischuck (Dorm L)	X		X		X	X	X		2
Residence Hall M	X		X		X	X	X		2
Dobbs Residence Hall	X					X	X		2
Dowell Residence Hall (Dorm G)	X					X	X		2
Duncan Residence Hall (Dorm B)	X					X	X		2
Dunn Residence Hall (Dorm E)	X					X	X		2
Graves Residence Hall (Dorm F)	X					X	X		2
Hollifield Residence Hall (Dorm A)	X					X	X		2
Knapp Residence Hall (Dorm H)	X					X	X		2
Toomer Residence Hall	X					X	X		2
CDV Apartment Bldg A	X					X	X		0
CDV Apartment Bldg B	X					X	X		0
CDV Apartment Bldg C	X					X	X		0
CDV Apartment Bldg D	X					X	X		0
CDV Apartment Bldg E	X					X	X		0
CDV Apartment Bldg F	X					X	X		0
Aubie Hall	X	X	X	X	X	X	X	X	2
Eagle Hall	X	X	X	X	X	X	X	X	2
Magnolia Hall	X	X	X	X	X	X	X	X	2
Oak Hall	X	X	X	X	X	X	X	X	2
Plainsmen Hall	X	X	X	X	X	X	X	X	2
Talon Hall	X	X	X	X	X	X	X	X	2
Tiger Hall	X	X	X	X	X	X	X	X	2
Willow Hall	X	X	X	X	X	X	X	X	2
Sewell Dorm						Smoke Alarms	X		1

Note: CDV Apartments were unoccupied in 2011. Sewell Hall became vacant in May 2011.

DESCRIPTION OF ON-CAMPUS FRATERNITY HOUSES

Note: Auburn University leases the land to the Fraternity House Corporations and the House Corporations are responsible for managing the properties identified in the table below. Fraternities are required to comply with the University's Fire Safety Program which requires a minimum of two fire and life safety inspections by a City of Auburn Fire Inspector and a minimum of two fire drills per year.

Item #	Building	Approximate Date Built	Number of Stories	Exit Signage	Smoke Alarms in Bedrooms	Monitored Fire Alarm System	Fire Extinguishers	Range Hood Fire Systems	Sprinkler System	Fire Evacuation Maps	Fire Drills
1	Alpha Gamma Rho 831 Lem Morrison Drive	1986	3	X	X	X	X	X	X	X	2
2	Alpha Psi 180 Wire Road	1963	1	X	X	X	X	X		X	2
3	Beta Theta Pi 930 Lem Morrison Drive	1984	3	X	X	X	X	X	X	X	2
4	Delta Chi 530 Biggio Drive	1981	2	X	X	X	X	X	X	X	2
5	Delta Sigma Phi Lem Morrison Drive	1995	2	X	X	X	X	X	X	X	2
6	Farm House 522 West Thach Avenue	1966	1	X	X	X	X	X	X	X	2
7	<i>Kappa Alpha Order</i> 940 Lem Morrison Drive	2005	2	X	X	X	X	X	X	X	2
8	Phi Delta Theta – no bedrooms 848 Lem Morrison Drive	1989	1	X	N/A	X	X	X	X	N/A	2
9	Phi Kappa Tau 841 West Magnolia Avenue	1950	2	X	X	X	X	X	X	X	2
10	Pi Kappa Phi 861 Lem Morrison Drive	1987	1	X	X	X	X	X	X	X	2
11	Sigma Chi 737 West Magnolia Avenue	1953	2	X	X	X	X	X	X	X	2
12	Sigma Nu 715 West Magnolia Avenue	1997	2	X	X	X	X	X	X	X	2
13	Sigma Phi Epsilon 926 West Magnolia Avenue	1976	2	X	X	X	X	X	X	X	2
14	Sigma Pi 960 West Magnolia Avenue	1983	2	X	X	X	X	X	X	X	2
15	Tau Kappa Epsilon 554 West Thach Avenue	1965	1	X	X	X	X	X	X	X	2
16	Theta Chi 935 Lem Morrison Drive	2007	2	X	X	X	X	X	X	X	2
17	Theta Xi 835 West Magnolia Avenue	1963	2	X	X	X	X	X	X	X	2

FIRE DRILLS

Each on campus dormitory building and fraternity residences has two mandatory fire evacuation drills annually conducted and evaluated by the City of Auburn Fire Division. Fire drills are required by Alabama law and all residents are required to participate if present. Evacuation is required in all instances. No residents may remain in the building during the fire drill. Residents must remain outside until cleared to return. Procedures for evacuation are explained at the first residence hall meeting which is held within the first few weeks of school.

STUDENT HOUSING POLICIES ON PORTABLE ELECTRICAL APPLIANCES, SMOKING AND OPEN FLAMES

Appliances

- 1.1.1 Extension Cords:** The use of extension cords in the residence halls is prohibited.
- 1.1.2 Hill/Quad Residence Halls:** Appliances that are prohibited include, but are not limited to: air-conditioning units, ceiling fans, halogen lamps, microwaves exceeding 700 watts, refrigerators exceeding 4.3 cubic feet, crock pots, dishwashers, hot plates, toaster ovens, toasters, washers and dryers, space heaters, appliances with open or exposed heating coils, and those which pose an electrical overload hazard.
- 1.1.3 Village Residence Halls:** Appliances that are prohibited include, but are not limited to: air-conditioning units, ceiling fans, halogen lamps, personal microwaves exceeding 700 watts, personal refrigerators exceeding 4.3 cubic feet, dishwashers, hot plates, toaster ovens, washers and dryers, space heaters, appliances with open or exposed heating coils, and those which pose an electrical overload hazard.

Holiday Decorations

- 1.4.7** The use of natural cut trees, branches, or greens is prohibited. Failure to disconnect all electrified decorations prior to leaving for semester break is prohibited.

Fire Safety

- 1.6.1 Arson:** Intentionally causing damage to a building by starting or maintaining a fire or explosion is prohibited.
- 1.6.2 Candles/Incense:** The burning of candles and/or incense is prohibited. Candles with burnt wicks are prohibited.
- 1.6.3 Evacuation Procedures:** Interference with or non-adherence to emergency evacuation procedures in the residence halls during a fire drill are prohibited. Returning to the residence halls before the "all-clear" signal has been given after a fire drill is prohibited.
- 1.6.4 Fireworks/Explosive Materials:** The storage, possession, or use of any type of fireworks, firecracker, or explosive material in the residence halls or surrounding vicinity is prohibited.
- 1.6.5 Flammable Materials/Liquids**
The storage, possession, or use of flammable materials/liquids in the residence halls is prohibited. Gas grills and gas cylinders/tanks are prohibited.
- 1.6.6 Vandalism of Safety Equipment:**
Removal, tampering with, and/or the disabling of pull stations, smoke or heat detectors, fire extinguishers, sprinkler heads or other life safety equipment is prohibited.
- 1.6.7 False Fire Alarms:**
Pulling a fire alarm station without due cause and /or falsely reporting a fire emergency to police or fire department is prohibited.

Smoking

- 3.5** Smoking is prohibited in or within 15 feet of the residence halls. Smokers must properly dispose of cigarette butts. Hookahs are prohibited in the residence halls and/or surrounding area.

Cooking

There are common kitchens located in all residence halls. Do not leave cooking food unattended. Do not cook food (such as popcorn) too long in the microwave as it will burn, smoke and set off alarms. The Fire Department is summoned automatically when the smoke alarms go off. Village residents: do not use the popcorn button on your microwave. ***If your negligence causes the Fire Department to respond, you will be charged \$150. If there are damages, you will be charged the cost of cleanup/restoration.***

Electrical Outlet Use

Overloading electrical outlets poses a serious fire hazard. You are asked to keep plugged in only those appliances that require constant use (refrigerator, clock, etc.) and to alternate other appliances as needed. If a circuit breaker is tripped, contact the Housing Property Management Office. Extension cords are not allowed; please use surge protector strips with circuit breakers.

Fire Safety

If you discover a fire, pull the nearest fire alarm and call the Fire Department immediately by dialing 911. Fire drills are required by Alabama law and all residents are required to participate if present. Procedures for evacuation are explained at the required Community Meeting at the beginning of the academic year.

FIRE EVACUATION PROCEDURES FOR ALL CAMPUS BUILDINGS INCLUDING CAMPUS HOUSING

- *In the event of a fire or fire alarm:*
- Exit The Area Immediately
- Close all doors as you leave, taking keys and medications with you if possible. DO NOT delay evacuation to retrieve these items.
- Activate the closest fire alarm pull station along your evacuation route.
- Notify others as you leave.
- **Call 911** and report the emergency after you are out of the building and safe.

If the fire is small enough, you may attempt to extinguish it with a portable fire extinguisher, ONLY IF: The fire alarm pull station has been activated; 911 has been notified; you are properly trained.

- If leaving a room, feel the door with the back of your hand before opening it. Do not open any door that feels hot.
- If smoke is present, stay low. The best quality air is near the floor.
- Always use the stairs to exit upper floors.
- DO NOT use the elevator.
- Once the building is evacuated, do not re-enter it for any reason. Return to the building ONLY when instructed to do so by emergency responders or administrators.
- DO NOT return for personal belongings.
- Direct and assist visitors and persons with disabilities who appear to need direction or assistance.
- Notify Risk Management & Safety (RMS) at 334.844.4870 that a fire has occurred AFTER you exit the building.

If You Are Trapped and Cannot Evacuate

- Close any doors between you and the fire.
- If available, wedge wet towels or cloth materials along the bottom of the door to keep out smoke.
- Call 911 and notify the dispatcher of your location.
- Remain on the phone with the 911 dispatcher as long as possible.
- Break a window only as a last resort, such as needing oxygen to breathe.
- Use caution when breaking any window.

Response to Fire Alarms

- NEVER assume that a fire alarm is a false alarm.
- If the alarm sounds and/or emergency strobes begin to blink, evacuate immediately.

For additional information go to: <http://www.auburn.edu/administration/rms/pdf/fire-emergency.pdf>

FIRE SAFETY EDUCATION AND TRAINING PROGRAMS FOR STUDENTS, FACULTY AND STAFF

Housing and Residence Life provides a Life Safety Class and Portable Fire Extinguisher training annually for all Hall Directors, Resident Assistants, and Area Coordinators. General Fire Safety training is also provided to Sorority Officers and Members housed in the Village Dorms.

RMS – Fire Safety provides the following education/training to all other faculty, staff and students:

- Fraternity Fire Safety Education is mandatory for fraternity chapter fire marshals and chapter presidents. This class is held at the beginning of Fall and Spring Semesters.
- Portable Fire Extinguisher Training (upon request)
- Fire Protection Systems (upon request)

TITLES OF PERSONS/ORGANIZATION FOR STUDENTS AND EMPLOYEES TO REPORT THAT A FIRE OCCURRED

In event of a fire emergency, report the fire by dialing 911.

After the emergency, please contact Kenneth Harrison or MaryAnn MacKenzie. Fire Safety is responsible for investigating and tracking all university fires and recording them on a fire log. This information allows us to take proactive measures to reduce future occurrences.

Contact information is as follows:

Kenneth D. Harrison, Fire Safety Program Manager, harrik7@auburn.edu 334.703.7504

MaryAnn MacKenzie, Fire & Life Safety Specialist, mzm0036@auburn.edu 334.703.7173

Risk Management and Safety Main Office: 334.844.4870

Fire Log can be viewed on the <http://www.auburn.edu/administration/rms/fire.html>

PLANS FOR FUTURE IMPROVEMENTS IN FIRE SAFETY

We will continue to work collaboratively with the University's Facilities Division, Housing and Residential Life, Athletics, and other administrative offices to ensure plans for future renovations or new construction projects include the required fire protection systems and fire-rated building components. We will assume all inspection, testing, and maintenance responsibilities for new water-based fire protection systems, pre-engineered restaurant fire extinguishment systems, special hazard fire extinguishment systems and portable fire extinguishers upon completion of building projects to ensure these systems are maintained in accordance with State Fire Codes and to ensure the operational integrity of each system.

OTHER CAMPUS FIRE SAFETY PROTECTION SYSTEMS AND ACTIVITIES

The focus of this report has been to disclose fire safety standards and practices that have been instrumental in protecting our students residing in on-campus student housing facilities. The following pages identify other campus facility fire extinguishment systems and the services provided by the Fire Safety Staff that resulted in a fire safe campus in 2011.

INVENTORY OF AUBURN UNIVERSITY ON-CAMPUS FIRE PROTECTION SYSTEMS

Item #	Building	Dry Sprinkler System	Wet Sprinkler system	Pre-action Sprinkler	Fire Pump	Wet Standpipe System	Dry Standpipe System	Range Hood System	Halon 1301 System	FM-200 System	Dry Chemical System	Total Systems
1	3-D Art Building	1	1									2
2	Alumni Center								1			1
3	AU Hotel & Dixon Conference Ctr.		1		1	1		3				6
4	AU Medical Clinic		1		1					1		3
5	Biggin Hall		1									1
6	Biological Research Bldg.					1						1
7	Draughon Library					1			5			6
8	Cary Hall	1	1									2
9	Chemistry Bldg.					1						1
10	Corely Hall					1						1
11	CVM Hot Water Plant II		1							1		2
12	Facilities Bldg. # 5		1								1	2
13	Forest Products Lab	1	1									2
14	Forestry & Wildlife Science Bldg.		1		1	1						3
15	Foy Union					1		3				4
16	Haley Center		1		1	1					1	4
17	Hargis Hall		1									1
18	EHS Facility, Building 1		1									1
19	EHS Facility, Building 2 and 3		1								1	2
20	Hot Water Plant I		1									1
21	Jordan Hare Stadium	12			1		2					15
22	Jordan Hare Locker Room	1										1
23	Jule Collins Smith Museum of Art		1	1								2
24	Langdon Hall	1										1
25	Lowder Business Bldg.		1			1						2
26	Martin Aquatic Center		1									1
27	McWorter Center		1									1
28	NCAT (Industrial Park)		1									1
29	O. D. Smith Hall		1									1
30	Overton Rudd Auditorium Kitchen		1					1				2
31	Peet Theater (partial)		1		1							2
32	Pharmacy Bldg.				1	1						2
33	Poultry Science Lab		1		1	1		3				6
34	Ross Hall				1	1						2
35	Rouse Life Science Bldg.					1						1
36	Samford Hall				1	1						2

37	Sewell Dining Hall							1				1
38	Science Center Laboratory		1		1	1						3
39	Shelby Center	1			1	1						3
40	Student Center		1			1		4				6
41	Terrell Dining Hall							4				4
42	Textile Engineering Bldg.		2									2
43	Tichenor Hall		1									1
44	Upchurch Hall					1						1
45	Village View Dining Hall	1	1					5				7
46	Wilmore Lab	1	2									3
47	Women's Softball Complex							1				1
48	Dorm 1 Harper Hall	1	1			1						3
49	Dorm 2 Katie Broun Hall	1	1			1						3
50	Dorm 3 Little Hall	1	1			1						3
51	Dorm 4 Teague Hall	1	1			1						3
52	Dorm 5 Dowdell Hall	1	1			1						3
53	Dorm 6 Glenn Hall	1	1			1						3
54	Dorm 7 Lane Hall	1	1			1						3
55	Dorm 8 Lupton Hall	1	1			1						3
56	Dorm 9 Keller Hall	1	1			1						3
57	Dorm 10 Owen Hall	1	1			1						3
58	Dorm J Boyd Hall				1	1						2
59	Dorm K Sasnett Hall	1	1		1	1						4
60	Dorm L		1			1						2
61	Dorm M		1			1						2
62	Aubie Hall	1	1					2				4
63	Eagle Hall	1	1					1				3
64	Magnolia Hall	2	1		1			6				10
65	Oak Hall	2	1					6				9
66	Plainsmen Hall	1	1					1				3
67	Talon Hall	1	1					1				3
68	Tiger Hall	1	1					1				3
69	Willow Hall	2	1					6				9
70	AU Regional Airport Terminal		1									1
71	AU Track & Soccer Facility	1	1									2
72	Beard Eaves Coliseum		1									1
73	ALFA Ag. Services & Research Bldg.	1	1									2
74	Large Animal Teaching Hospital	2	2									4
75	Lowder Student Athletic Center		1									1
76	Science Center Auditorium		1									1
77	Science Classroom Bldg.		1									1
78	Ag. Heritage Pavillion	1										1

79	AG. Red Barn	1										1
80	Sparks Diagnostic Lab		1									1
81	District Energy Plant		1									1
82	Parking Deck						1					1
83	Thach Hall		1									1
84	T-Mobile Bldg.			1								1
85	Golf Teaching Facility	1										1
86	Miller Gorrie Bldg.	1										1
87	Extension Hall					1						1
88	Cary Hall	1	1									2
89	MRI Research Center	1		1								2
90	OIT Building	1		1	1							3
91	South Quad MultiModal	1					1					2
92	Aquatic Resource Center Admin		1									1
93	Aquatic Resource Center Lab		1									1
94	Indoor Practice Facility	1	1									2
95	Dawson Bldg	1						1				2
	Total Systems	56	68	4	16	33	4	50	6	2	3	242

CRITICAL AREAS OF RESPONSIBILITY OF THE FIRE SAFETY PROGRAM

Fire Safety Education and Training Programs	
Fraternity Fire Safety	2
Hands-on Fire Extinguisher Training	7
Consultations and Code Research	124
Other Fire Safety Topics	4
Total	137

Fire and Life Safety Plan Reviews	
Plan Reviews	103
Total	103

Fire Safety Permits issued	
Hot Work Permit	176
Fire Watch Permit	66
Request to Disable Fire Protection	69
Total	311

New Construction Fire & Life Safety Inspections	
Construction Projects	8
Fire Alarm Acceptance Inspections/Test	8
Sprinkler System Acceptance Inspections/Test	9
Fire Pump Acceptance Inspections/Test	1
Above Ceiling Inspections	36
Fire Flow Hydrant Test	16

Existing Building Fire and Life Safety Inspections	
Dorm Buildings Inspected (100%)	32
Business/Assembly/Storage Buildings	38
Building Renovations Inspected	8
New Buildings Inspected/Final	9
Total	87

Inspection, Testing & Maintenance of Water-based Fire Protection Systems & Extinguishers	
Weekly Fire Pump Test	800
Monthly Sprinkler System Inspections	1024
Quarterly Inspections/Test-Sprinkler Systems	384
Annual Sprinkler System Inspections/Test	128
Annual Fire Pump Test	16
Semi-Annual Special Hazard Systems	122
Monthly Fire Extinguisher Inspections	42,472
Annual Fire Extinguisher Service	4,261

Special Events	
Pre-game Stadium Inspections	9
Football Games	4
Other Events	26
Total	39

City of Auburn Fire Division Response Information			
Responses by Month		Responses by Incident	
January	30	Alarm Malfunctions	29
February	33	Activations/Unknown Cause	80
March	26	Cooking Alarms	63
April	30	Electrical Alarms	7
May	9	Accidental Alarms	52
June	19	Smoke Odor Investigations	9
July	26	Smoking	1
August	46	Alarms Caused by Steam	31
September	41	Water flow Alarms	4
October	43	Fire Causing Damage - Housing	0
November	46	Fires Causing Damage – Other Occupancies	1
December	24	Malicious Mischief Activations	22
		HazMat Incidents	1
		Other Fires	7
		Other Miscellaneous	54
		Dumpster Fires	1
		Natural Vegetation Fires	10
Total	373	Total Responses	373