



AUBURN  

---

UNIVERSITY

**2009**  
**ANNUAL FIRE SAFETY REPORT**

A document produced by Auburn University  
In compliance with the requirements of the  
Higher Education Opportunity Act

**Auburn University**  
**Risk Management and Safety**  
**316 Leach Science Center**  
**Auburn, Alabama 36849**  
**334.844.4870**

## **MESSAGE FROM THE FIRE SAFETY PROGRAM MANAGER**

On August 14, 2008 the Higher Education Opportunity Act (HEOA) was signed into law. Under HEOA, institutions that maintain on-campus student housing are required to publish an annual fire safety report that discloses campus fire safety practices and standards of the institution to the U.S. Department of Education, the campus community and to the general public. Components of this law are intended to help ensure America's college students, their parents and the public have uniform, valid and easy to understand information regarding an institution's fire safety practices and standards.

I'm pleased to provide the 2009 Annual Fire Safety Report. This report meets all HEOA requirements and will provide you with information on the services that were performed to ensure the safety and welfare of our students, faculty, staff, and visitors and minimize the disruption of university operations.

Auburn University's Risk Management and Safety, Fire Safety Program Staff are responsible for performing: fire safety education; code research and consultation; inspection, testing and maintenance of all special hazard fire extinguishment systems, water-based fire protection systems, and portable fire extinguishers; records management; fire and life safety plan reviews of new construction and renovation projects; inspection of new construction and new fire protection systems for code compliance and operational integrity; plus fire and life safety inspections of existing campus buildings. Our staff is committed to providing exceptional fire safety services to protect our campus which consists of 24,530 students, 1,188 faculty members and 5,298 staff members. Additionally, there are 429 buildings that house research, laboratories, classrooms, livestock and administrative offices. These facilities are spread over 1,841 acres of land and have a cumulative property value of \$3 billion.

To accomplish these services, the Fire Safety Staff maintains collaborative working relationships with other University departments and outside agencies to include: Faculty, Staff, Students, Facilities Division, Housing and Residential Life, Office of Greek Life, Athletics, University Public Safety and Security, the City of Auburn Public Safety Department (Fire Division, Inspections and Codes Enforcement Division, and the Police Division), State Fire Marshal's Office, State Building Commission, Contracted Architects, Engineers, Construction Project Managers, and Building/Fire Protection Contractors. This collaboration ensures maximum efficiency, fiscal responsibility and success in these areas of responsibility. We will continue to work diligently to meet the challenges and goal of providing a fire safe campus. I encourage you to partner with us in keeping Auburn University Fire Safe.

According to The Center for Campus Fire Safety from January 2000 to present, 71 fatal fires have been documented that occurred on a college campus, in Greek housing or in off-campus housing within 3-miles of campus, claiming a total of 102 victims.

*I'm pleased to report there were no fire fatalities, fire related injuries, loss of revenue or property damage on the campus of Auburn University during 2009.*

If you have any questions about campus fire safety or this report, please don't hesitate to contact me at 334.844.4870 or email me at [harrik7@auburn.edu](mailto:harrik7@auburn.edu).

*Kenneth D. Harrison*

## **MISSION STATEMENT**

To ensure the safety and welfare of University students, faculty, staff and visitors, protect the University's infrastructure, and minimize disruption of academic programs through fire prevention and life safety code efforts.

## **PROGRAM STAFF**

Kenneth D. Harrison, Fire Safety Program Manager  
MaryAnn MacKenzie, Fire & Life Safety Specialist  
Patricia Davis, Fire and Life Safety Technician

## **2009 FIRE STATISTICS FOR ON-CAMPUS STUDENT HOUSING**

<b>Item</b>	<b>Location</b>	<b>Fire Cause</b>	<b>Number of Injuries</b>	<b>Number of Deaths</b>	<b>Property Damage Value</b>
1	CDV Building-A	No Fire	0	0	\$0
2	CDV Building-B	No Fire	0	0	\$0
3	CDV Building-C	No Fire	0	0	\$0
4	CDV Building-D	No Fire	0	0	\$0
5	CDV Building-E	No Fire	0	0	\$0
6	CDV Building-F	No Fire	0	0	\$0
7	Dorm 1-Harper	No Fire	0	0	\$0
8	Dorm 2-Broun	No Fire	0	0	\$0
9	Dorm 3-Little	No Fire	0	0	\$0
10	Dorm 4-Teague	No Fire	0	0	\$0
11	Dorm 5-Dowdell	No Fire	0	0	\$0
12	Dorm 6-Glenn	No Fire	0	0	\$0
13	Dorm 7-Lane	No Fire	0	0	\$0
14	Dorm 8-Lupton	No Fire	0	0	\$0
15	Dorm 9-Keller	No Fire	0	0	\$0
16	Dorm 10-Owen	No Fire	0	0	\$0
17	Dorm A-Hollifield	No Fire	0	0	\$0
18	Dorm B-Duncan	No Fire	0	0	\$0
19	Dorm C-Toomer	No Fire	0	0	\$0
20	Dorm D-Dobbs	No Fire	0	0	\$0
21	Dorm E-Dunn	No Fire	0	0	\$0
22	Dorm F-Graves	No Fire	0	0	\$0
23	Dorm G-Dowell	No Fire	0	0	\$0
24	Dorm H-Knapp	No Fire	0	0	\$0
25	Dorm J-Boyd	No Fire	0	0	\$0
26	Dorm K-Sasnett	No Fire	0	0	\$0
27	Dorm L-Leischuck	No Fire	0	0	\$0

Item	Location	Fire Cause	Number of Injuries	Number of Deaths	Property Damage Value
28	Dorm M	No Fire	0	0	\$0
29	Village - Aubie	No Fire	0	0	\$0
30	Village - Eagle	No Fire	0	0	\$0
31	Village - Magnolia	No Fire	0	0	\$0
32	Village - Oak	No Fire	0	0	\$0
33	Village - Plainsman	No Fire	0	0	\$0
34	Village - Talon	No Fire	0	0	\$0
35	Village - Tiger	No Fire	0	0	\$0
36	Village - Willow	No Fire	0	0	\$0
37	Sewell Hall	No Fire	0	0	\$0
38	Alpha Gamma Rho	No Fire	0	0	\$0
39	Alpha Psi	No Fire	0	0	\$0
40	Beta Theta Pi	No Fire	0	0	\$0
41	Delta Chi	No Fire	0	0	\$0
42	Delta Sigma Phi	No Fire	0	0	\$0
43	Farm House Fraternity	No Fire	0	0	\$0
44	Kappa Alpha Order	No Fire	0	0	\$0
45	Phi Delta Theta	No Fire	0	0	\$0
46	Phi Kappa Tau	No Fire	0	0	\$0
47	Pi Kappa Phi	No Fire	0	0	\$0
48	Sigma Chi	Natural (Grass Fire)	0	0	\$0
49	Sigma Nu	No Fire	0	0	\$0
50	Sigma Phi Epsilon	No Fire	0	0	\$0
51	Sigma Pi	No Fire	0	0	\$0
52	Tau Kappa Epsilon	No Fire	0	0	\$0
53	Theta Chi	No Fire	0	0	\$0
54	Theta Xi	No Fire	0	0	\$0
	<b>Total Fires</b>	<b>1 Natural (Grass Fire)</b>	<b>0</b>	<b>0</b>	<b>\$0</b>

## **DESCRIPTION OF ON-CAMPUS HOUSING AND FIRE SAFETY SYSTEMS**

### **HILL DORMS**

The Hill consists of twelve dormitory buildings with a total capacity of 1,482. There are 716 double occupancy rooms and 50 single occupancy rooms.

### **Hollifield Residence Hall (Dorm A), 285 West Samford Avenue**

Built in 1962 and renovated in 1988, Dorm A is a three-story building with a basement. The building contains 29,680 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Duncan Residence Hall (Dorm B), 295 West Samford Avenue**

Built in 1962 and renovated in 1988, Dorm B is a three-story building with a basement. The building contains 27,744 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Toomer Residence Hall (Dorm C), 437 Duncan Drive**

Built in 1962 and renovated in 1988, Dorm C is a three-story building with a basement. The building contains 29,656 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Dobbs Residence Hall (Dorm D), 345 West Samford Avenue**

Built in 1965 and renovated in 1988, Dorm D is a three-story building with a basement. The building contains 27,676 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Dunn Residence Hall (Dorm E), 435 Duncan Drive**

Built in 1965 and renovated in 1989, Dorm E is a three-story building with a basement. The building contains 27,676 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Graves Residence Hall (Dorm F), 439 Duncan Drive**

Built in 1965 and renovated in 1989, Dorm F is a three-story building with a basement. The building contains 27,687 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Dowell Residence Hall (Dorm G), 320 PO Davis Drive**

Built in 1965 and renovated in 1989, Dorm G is a three-story building with a basement. The building contains 31,445 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Knapp Residence Hall (Dorm H), 302 PO Davis Drive**

Built in 1966 and renovated in 1989, Dorm H is a three-story building with a basement. The building contains 31,434 square feet and can house 107 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a zoned fire alarm system.
- The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Boyd Residence Hall (Dorm J), 280 PO Davis Drive**

Built in 1967 and renovated in 1990, Dorm J is a six-story building with a basement. The building contains 59,917 square feet and can house 212 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 2-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.
- An emergency generator is provided and supplies back-up power for all fire and life safety systems (i.e. fire pump, fire alarm system, emergency lights/exit signs).

### **Sasnett Residence Hall (Dorm K), 350 PO Davis Drive**

Built in 1967 and renovated in 1990, Dorm K is a six-story building with a basement. The building contains 60,898 square feet and can house 212 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 2-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.
- An emergency generator is provided and supplies back-up power for all fire and life safety systems (i.e. fire pump, fire alarm system, emergency lights/exit signs).

### **Leischuck Residence Hall (Dorm L), 501 Duncan Drive**

Built in 1994, Dorm L is a four-story building. The building contains 31,156 square feet and can house 101 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with zoned smoke detectors that are monitored by a zoned fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Residence Hall M (Dorm M), 282 PO Davis Drive**

Built in 1994, Dorm M is a four-story building. The building contains 31,156 square feet and can house 101 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with zoned smoke detectors that are monitored by a zoned fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **QUAD DORMS**

The Quad consists of ten dormitory buildings with a total capacity of 967. There are 463 double occupancy rooms and 41 single occupancy rooms.



### **Harper Residence Hall (Dorm 1), 226 Mell Street**

Built in 1938 and renovated in 1994, Dorm 1 is a three-story building with a basement. The building contains 20,868 square feet and can house 78 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Broun Residence Hall (Dorm 2), 246 Mell Street**

Built in 1938 and renovated in 1994, Dorm 2 is a three-story building with a basement. The building contains 23,316 square feet and can house 101 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Little Residence Hall (Dorm 3), 304 Quad Drive**

Built in 1938 and renovated in 1996, Dorm 3 is a three-story building with a basement. The building contains 26,734 square feet and can house 90 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored in a central location 24/7.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Teague Residence Hall (Dorm 4), 302 Quad Drive**

Built in 1938 and renovated in 1996, Dorm 4 is a three-story building with a basement. The building contains 23,370 square feet and can house 90 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored in a central location 24/7.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Dowdell Residence Hall (Dorm 5), 266 Mell Street**

Built in 1957 and renovated in 1999, Dorm 5 is a three-story building with a basement. The building contains 23,576 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Glenn Residence Hall (Dorm 6), 262 Roosevelt Drive**

Built in 1957 and renovated in 1999, Dorm 6 is a three-story building with a basement. The building contains 23,552 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Lane Residence Hall (Dorm 7), 301 Quad Drive**

Built in 1957 and renovated in 1997, Dorm 7 is a three-story building with a basement. The building contains 21,868 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Lupton Residence Hall (Dorm 8), 300 Roosevelt Drive**

Built in 1957 and renovated in 1997, Dorm 8 is a three-story building with a basement. The building contains 21,868 square feet and can house 88 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Keller Residence Hall (Dorm 9), 329 Quad Drive**

Built in 1957 and renovated in 1998, Dorm 9 is a three-story building with a basement. The building contains 21,868 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Owen Residence Hall (Dorm 10), 330 Roosevelt Drive**

Built in 1957 and renovated in 1998, Dorm 10 is a three-story building with a basement. The building contains 23,085 square feet and can house 104 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms and common areas are equipped with addressable smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **THE VILLAGE DORMS**

The Village consists of eight dormitory buildings with a total capacity of 1,666. Buildings share a fire pump.

#### **Magnolia Residence Hall, 201-E Wire Road**

Built in 2009, Magnolia Hall is a four-story building with two, three and four bedroom suites. The building contains 105,322 square feet, and can house 233 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors, stairwells and assembly areas.
- All suites are equipped with addressable smoke detectors in each bedroom and the common living areas with in each suit. All smoke detection devices are monitored by the building fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

#### **Oak Residence Hall, 201-F Wire Road**

Built in 2009, Oak Hall is a four-story building with two, three and four bedroom suites. The building contains 108,104 square feet and can house 246 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors, stairwells and assembly areas.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Willow Residence Hall, 201-D Wire Road**

Built in 2009, Willow Hall is a four-story building with two, three and four bedroom suites. The building contains 108,104 square feet and can house 246 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Aubie Residence Hall, 201-H Wire Road**

Built in 2009, Aubie Hall is a four-story building with two, three and four bedroom suites. The building contains 107,755 square feet and can house 309 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire Evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Eagle Residence Hall, 201-G Wire Road**

Built in 2009, Eagle Hall is a four-story building with two, three and four bedroom suites. The building contains 58,108 square feet and can house 153 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Tiger Residence Hall, 201-C Wire Road**

Built in 2009, Tiger Hall is a four-story building with two, three and four bedroom suites. The building contains 58,108 square feet and can house 153 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Talon Residence Hall, 201-A Wire Road**

Built in 2009, Tiger Hall is a four-story building with two, three and four bedroom suites. The building contains 60,439 square feet and can house 163 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

### **Plainsman Residence Hall, 201-B Wire Road**

Built in 2009, Plainsman Hall is a four-story building with two, three and four bedroom suites. The building contains 60,439 square feet and can house 163 students. The structural members including floors, ceilings and walls are wood frame with brick veneer.

- All exit corridors and stairwells have a minimum of 1-hour fire rating.
- All bedrooms are equipped with electrical hardwired smoke alarms and the common areas are equipped with smoke detectors that are monitored by a fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- An automatic sprinkler system, standpipe system and fire pump is provided.
- Portable fire extinguishers are provided in all exit corridors.
- Fire evacuation maps are posted inside each bedroom, at elevator lobbies and stairwell entrances.

## **CAROLINE DRAUGHON VILLAGE APARTMENTS**

Caroline Draughon Village (CDV) consists of six three- story residential apartment buildings. The six buildings total 120,468 square feet and can house up to 552 students. The structural members including floors, ceilings and walls are concrete with brick veneer.

### **CDV Apartment Building A, 731 Extension Drive**

Built in 1980, CDV Apartment Building A is a three- story building with 17,765 square feet consisting of 21 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

### **CDV Apartment Building B, 721 Extension Drive**

Built in 1980, CDV Apartment Building B is a three- story building with 21,533 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

### **CDV Apartment Building C, 280 Wire Road**

Built in 1980, CDV Apartment Building C is a three- story building with 20,334 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

### **CDV Apartment Building D, 290 Wire Road**

Built in 1980, CDV Apartment Building D is a three-story building with 21,533 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

### **CDV Apartment Building E, 751 Extension Drive**

Built in 1980, CDV Apartment Building E is a three-story building with 20,339 square feet consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

### **CDV Apartment Building F, 741 Extension Drive**

Built in 1980, CDV Apartment Building F is a three-story building with 18,959 square feet consisting of 21 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with brick veneer.

- Built in 1979, CDV Apartment Building F is a two-story building consisting of 24 apartment units. Each unit has two bedrooms and can sleep four students. The building is a concrete building with a brick veneer finish. Each unit opens onto an exterior corridor.
- Exits are marked with illuminated exit signs and emergency lighting is provided in corridors and stairwells.
- All bedrooms are equipped with addressable smoke detectors that are monitored by an addressable fire alarm system. The fire alarm system is monitored 24/7 in a central location.
- Portable fire extinguishers are provided in all exit balconies as well as in each apartment.
- Fire evacuation maps are posted inside each bedroom.

### **SEWELL HALL DORM, 391 South Donahue Drive**

Built in 1962, Sewell Hall Dorm is a three-story building with 24,689 square feet consisting of bedroom 72 units. The building is a concrete building with brick veneer.

- All bedrooms are equipped with battery operated smoke alarms and a portable fire extinguisher.
- Each unit opens onto an exterior corridor.



**TABLE OF AUBURN UNIVERSITY ON-CAMPUS HOUSING FIRE SAFETY SYSTEMS**

Building	Fire Alarm system	Dry Sprinkler	Wet Sprinkler	Fire Pump	Wet Standpipe	Smoke Detection	Fire Extinguishers	Range-Hood Fire Systems	Number of Fire Drills
Harper Hall (Dorm 1)	X	X	X		X	X	X		2
Broun Hall (Dorm 2)	X	X	X		X	X	X		2
Little Hall (Dorm 3)	X	X	X		X	X	X		2
Teague Hall (Dorm 4)	X	X	X		X	X	X		2
Dowdell Hall (Dorm 5)	X	X	X		X	X	X		2
Glenn Hall (Dorm 6)	X	X	X		X	X	X		2
Lane Hall (Dorm 7)	X	X	X		X	X	X		2
Lupton Hall (Dorm 8)	X	X	X		X	X	X		2
Keller Hall (Dorm 9)	X	X	X		X	X	X		2
Owen Hall (Dorm 10)	X	X	X		X	X	X		2
Boyd Hall (Dorm J)	X	X	X	X	X	X	X		2
Sasnett Hall (Dorm K)	X	X	X	X	X	X	X		2
Leischuck (Dorm L)	X		X		X	X	X		2
Residence Hall M	X		X		X	X	X		2
Dobbs Residence Hall	X					X	X		2
Dowell Residence Hall (Dorm G)	X					X	X		2
Duncan Residence Hall (Dorm B)	X					X	X		2
Dunn Residence Hall (Dorm E)	X					X	X		2
Graves Residence Hall (Dorm F)	X					X	X		2
Hollifield Residence Hall (Dorm A)	X					X	X		2
Knapp Residence Hall (Dorm H)	X					X	X		2
Toomer Residence Hall	X					X	X		2
CDV Apartment Bldg A	X					X	X		0
CDV Apartment Bldg B	X					X	X		0
CDV Apartment Bldg C	X					X	X		0
CDV Apartment Bldg D	X					X	X		0
CDV Apartment Bldg E	X					X	X		0
CDV Apartment Bldg F	X					X	X		0
Aubie Hall	X	X	X	X	X	X	X	X	2
Eagle Hall	X	X	X	X	X	X	X	X	2
Magnolia Hall	X	X	X	X	X	X	X	X	2
Oak Hall	X	X	X	X	X	X	X	X	2
Plainsmen Hall	X	X	X	X	X	X	X	X	2
Talon Hall	X	X	X	X	X	X	X	X	2
Tiger Hall	X	X	X	X	X	X	X	X	2
Willow Hall	X	X	X	X	X	X	X	X	2
Sewell Dorm						Smoke Alarms	X		

**Note:** CDV Apartments were unoccupied in 2009.

**DESCRIPTION OF ON-CAMPUS FRATERNITY HOUSES**

**Note:** Auburn University leases the land to the Fraternity House Corporations and the House Corporations are responsible for managing the properties identified in the table below. Fraternities are required to comply with the University’s Fire Safety Program which requires a minimum of two fire and life safety inspections by a City of Auburn Fire Inspector and a minimum of two fire drills per year.

Item #	Building	Approximate Date Built	Number of Stories	Exit Signage	Smoke Alarms in Bedrooms	Monitored Fire Alarm System	Fire Extinguishers	Range Hood Fire Systems	Sprinkler System	Fire Evacuation Maps	Fire Drills
1	Alpha Gamma Rho 831 Lem Morrison Drive	1986	3	X	X	X	X	X	X	X	2
2	Alpha Psi 180 Wire Road	1963	1	X	X	X	X	X		X	2
3	Beta Theta Pi 930 Lem Morrison Drive	1984	3	X	X	X	X	X	X	X	2
4	Delta Chi 530 Biggio Drive	1981	2	X	X	X	X	X	X	X	2
5	Delta Sigma Phi Lem Morrison Drive	1995	2	X	X	X	X	X	X	X	2
6	Farm House 522 West Thach Avenue	1966	1	X	X	X	X	X	X	X	2
7	Kappa Alpha Order 940 Lem Morrison Drive	2005	2	X	X	X	X	X	X	X	2
8	Phi Delta Theta – no bedrooms 848 Lem Morrison Drive	1989	1	X	N/A	X	X	X		N/A	2
9	Phi Kappa Tau 841 West Magnolia Avenue	1950	2	X	X	X	X	X	X	X	2
10	Pi Kappa Phi (Under Renovation) 861 Lem Morrison Drive	1987	1								2
11	Sigma Chi 737 West Magnolia Avenue	1953	2	X	X	X	X	X	X	X	2
12	Sigma Nu 715 West Magnolia Avenue	1997	2	X	X	X	X	X	X	X	2
13	Sigma Phi Epsilon 926 West Magnolia Avenue	1976	2	X	X	X	X	X	X	X	2
14	Sigma Pi 960 West Magnolia Avenue	1983	2	X	X	X	X	X	X	X	2
15	Tau Kappa Epsilon 554 West Thach Avenue	1965	1	X	X	X	X	X	X	X	2
16	Theta Chi 935 Lem Morrison Drive	2007	2	X	X	X	X	X	X	X	2
17	Theta Xi 835 West Magnolia Avenue	1963	2	X	X	X	X	X	X	X	2

**FIRE DRILLS**

Each on campus dormitory building and fraternity residences has two mandatory fire evacuation drills annually conducted and evaluated by the City of Auburn Fire Division. Fire drills are required by Alabama law and all residents are required to participate if present. Evacuation is required in all instances. No residents may remain in the building during the fire drill. Residents must remain outside until cleared to return. Procedures for evacuation are explained at the first residence hall meeting which is held within the first few weeks of school.

## **STUDENT HOUSING POLICIES ON PORTABLE ELECTRICAL APPLIANCES, SMOKING AND OPEN FLAMES**

### **Appliances**

Follow instructions and precautions for proper use of all appliances. Appliances allowed in residence halls include: coffee makers, curling irons, hair dryers, popcorn poppers, personal computers, stereos, televisions, window fans, George Foreman-type indoor electric grills, micro fridges, microwaves (not to exceed 700 watts), refrigerators (not to exceed 4.3 cubic feet). Roommates/suitemates may not 'combine' wattage limits to install a larger microwave or refrigerator.

Appliances **prohibited** in resident halls include: air conditioning units, ceiling fans, halogen lamps, crock pots, dishwashers, hot plates, toaster ovens, toasters, washers and dryers, space heaters and appliances with open flames or heating coils, or which pose an electrical overload.

### **Smoking**

Smoking is prohibited in university housing. Smoking is not permitted in residence hall suites, or public areas (including building entrances and exterior doors) of buildings.

### **Candles/Incense**

Candles and incense may not be burned. Candles with burned wicks are not allowed. There's an automatic \$50 fine for having a lit candle or for burning incense. Decorative candles with unburned wicks are allowed.

### **Cooking**

Don't leave cooking food unattended. Don't cook food (such as popcorn) too long in the microwave as it will burn, smoke and set off alarms. This will summon the fire department.

### **Holiday Decorations**

State fire code regulations prohibit "extremely flammable" holiday decorations in residence hall rooms and apartments. Artificial trees or live Christmas trees growing in pots are acceptable. All electrified decorations must be taken down and completely disconnected from wall power sources before residents leave for break.

### **Flammable Materials/Liquids**

Use and storage of flammable materials/liquids in residential facilities is strictly prohibited. Fire hazards such as newspaper stacks, excessive trash, improper wiring, and open flames (including candles and incense) are not permitted. Decorative candles are allowed with un-burned wicks. Gas grills and gas cylinders/tanks are prohibited.

### **Fireworks**

The use and possession of fireworks or other forms of explosives is strictly prohibited.

### **Electrical Outlet Use**

Overloading electrical outlets poses a serious fire hazard. Residents should keep plugged in only those appliances that require constant use (refrigerator, clock, etc.) and to alternate other appliances when needed. If a circuit breaker is tripped, contact the Housing Property Management Office. Extension cords are not allowed. Only surge protector strips with circuit breakers are allowed. (Ask maintenance about surge strips with long cords.)

## **Smoke Detectors**

Smoke detectors are not to be disabled. Please remember that these detectors are for your welfare, and the welfare of the entire building. Disabling a smoke detector is vandalism, and will lead to disciplinary measures.

## **Fire**

If you discover a fire, pull the nearest fire alarm and call the Fire Department immediately by dialing 911. Discharging a fire extinguisher as a prank results in an automatic fine, and will be considered vandalism of safety equipment.

## **Arson**

Intentionally causing damage to a building by starting a fire or causing an explosion is considered arson. This is not a practical joke and is taken very seriously. Conviction carries stiff penalties such as fines and incarceration.

For additional information go to: <https://fp.auburn.edu/housing/pdf/guide.pdf>

## **FIRE EVACUATION PROCEDURES FOR ALL CAMPUS BUILDINGS INCLUDING CAMPUS HOUSING**

- Exit The Area Immediately
- Close all doors as you leave, taking keys and medications with you if possible. DO NOT delay evacuation to retrieve these items. DO NOT return for personal belongings.
- Activate the closest fire alarm pull station along your evacuation route.
- Notify others as you leave.
- Call 911 and report the emergency after you are out of the building and safe.
- Attempt to extinguish a small fire with a portable fire extinguisher, ONLY IF: The fire alarm pull station has been activated; 911 has been notified; you are properly trained on the use of fire extinguishers.
- Before leaving a room, feel the door with the back of your hand before opening it. Do not open any door that feels hot.
- If smoke is present, stay low. The best quality air is near the floor.
- Always use the stairs to exit upper floors. DO NOT use the elevator.
- Direct and assist visitors and persons with disabilities who appear to need direction or assistance.
- Once the building is evacuated, do not re-enter for any reason. Return to the building ONLY when instructed to do so by emergency responders or administrators.
- Notify Risk Management & Safety at 334.844.4870 that a fire has occurred AFTER you exit the building.

## **If You Are Trapped and Cannot Evacuate**

- Close any doors between you and the fire.
- If available, wedge wet towels or cloth materials along the bottom of the door to keep out smoke.
- Call 911 and notify the dispatcher of your location.
- Remain on the phone with the 911 dispatcher as long as possible.
- Break a window only as a last resort, such as needing oxygen to breathe. Use caution when breaking any window.

## **Response to Fire Alarms**

- NEVER assume that a fire alarm is a false alarm.
- If the alarm sounds and/or emergency strobes begin to blink, evacuate immediately.

For additional Information go to: <http://www.auburn.edu/administration/rms/pdf/fire-emergency.pdf>

## **FIRE SAFETY EDUCATION AND TRAINING PROGRAMS FOR STUDENTS, FACULTY AND STAFF**

Housing and Residence Life provides a Life Safety Class and Portable Fire Extinguisher training annually for all Hall Directors, Resident Assistants, and Area Coordinators. This training is also provided to Sorority Officers and Members housed in the Village Dorms.

Risk Management and Safety provides the following education/training to all other faculty, staff and students:

- Fraternity Fire Safety Education is mandatory for fraternity chapter fire marshals and chapter presidents. This class is held at the beginning of Fall and Spring Semesters.
- Portable Fire Extinguisher Training (upon request)
- Fire Protection Systems (upon request)

## **TITLES OF PERSONS/ORGANIZATION FOR STUDENTS AND EMPLOYEES TO REPORT THAT A FIRE OCCURRED**

In event of a fire emergency, report the fire by dialing 911.

After the emergency, please contact Kenneth Harrison or MaryAnn MacKenzie. Fire Safety is responsible for investigating and tracking all university fires and recording them on a fire log. This information allows us to take proactive measures to reduce future occurrences.

Contact information is as follows:

Kenneth D. Harrison, Fire Safety Program Manager, [harrik7@auburn.edu](mailto:harrik7@auburn.edu) 334.703.7504

MaryAnn MacKenzie, Fire & Life Safety Specialist, [mzm0036@auburn.edu](mailto:mzm0036@auburn.edu) 334.703.7173

Risk Management and Safety Main Office: 334.844.4870

Fire Log can be viewed on the <http://www.auburn.edu/administration/rms/fire.html>

## **PLANS FOR FUTURE IMPROVEMENTS IN FIRE SAFETY**

Risk Management and Safety will continue to work collaboratively with the University's Facilities Division, Housing and Residential Life, and other administrative offices to ensure plans for future renovations or new construction projects include the required fire protection systems and fire rated building components. Standard Operating Guidelines (SOG's) are in development and will be posted on the Risk Management and Safety website. The SOG's include: Fire Evacuation Guidelines, Fireworks/Pyrotechnics Approval Guidelines, Storage of Liquefied Petroleum Gas Cylinders, Safe Use of Barbeque Grills, Holiday Decorations, Outage Notifications of Building/Campus Services, Hot Work Permit Process, Frequently Asked Questions, Portable Generator Safety Bulletin, and the Fraternity Fire Safety Program.

## **OTHER CAMPUS FIRE SAFETY PROTECTION SYSTEMS AND ACTIVITIES**

The focus of this report has been to disclose fire safety standards and practices that have been instrumental in protecting our students residing in on-campus student housing facilities. The following pages identify other campus facility fire extinguishment systems and the services provided by the Fire Safety Staff that resulted in a fire safe campus in 2009.

**INVENTORY OF AUBURN UNIVERSITY ON-CAMPUS FIRE PROTECTION SYSTEMS**

Item #	Building	Dry Sprinkler System	Wet Sprinkler system	Pre-action Sprinkler	Fire Pump	Wet Standpipe System	Dry Standpipe System	Range Hood System	Halon 1301 System	FM-200 System	Dry Chemical System	Total Systems
1	3-D Art Building	1	1									2
2	Alumni Center								1			1
3	AU Hotel & Dixon Conference Ctr.		1		1	1		3				6
4	AU Medical Clinic		1		1					1		3
5	Biggin Hall		1		1							2
6	Biological Research Bldg.					1						1
7	Draughon Library					1			5			6
8	Cary Hall	1	1									2
9	Chemistry Bldg.					1						1
10	Corely Hall					1						1
11	CVM Hot Water Plant II		1							1		2
12	Facilities Bldg. # 5		1								1	2
13	Forest Products Lab	1	1									2
14	Forestry & Wildlife Science Bldg.		1		1	1						3
15	Foy Union					1		3				4
16	Haley Center		1		1	1					1	4
17	Hargis Hall		1									1
18	EHS Facility, Building 1		1									1
19	EHS Facility, Building 2 and 3		1								1	2
20	Hot Water Plant I		1									1
21	Jordan Hare Stadium	1			1		1					3
22	Jordan Hare Locker Room	1										1
23	Jule Collins Smith Museum of Art		1	1								2
24	Langdon Hall	1										1
25	Lowder Business Bldg.		1			1						2
26	Martin Aquatic Center		1									1
27	McWorter Center		1									1
28	NCAT (Industrial Park)		1									1
29	O. D. Smith Hall		1									1
30	Overton Rudd Auditorium Kitchen							1				1
31	Peet Theater (partial)		1		1							2
32	Pharmacy Bldg.				1	1						2
33	Poultry Science Lab		1		1	1		3				6

Item #	Building	Dry Sprinkler System	Wet Sprinkler system	Pre-action Sprinkler	Fire Pump	Wet Standpipe System	Dry Standpipe System	Range Hood System	Halon 1301 System	FM-200 System	Dry Chemical System	Total Systems
34	Ross Hall				1	1						2
35	Rouse Life Science Bldg.					1						1
36	Samford Hall				1	1						2
37	Sewell Dining Hall							1				1
38	Science Center Laboratory		1		1	1						3
39	Shelby Center		1		1	1						3
40	Student Center		1			1		4				6
41	Terrell Dining Hall							4				4
42	Textile Engineering Bldg.		1									1
43	Tichenor Hall		1									1
44	Upchurch Hall					1						1
45	Village View Dining Hall	1	1					5				7
46	Wilmore Lab	1	2									3
47	Women's Softball Complex							1				1
48	Dorm 1 Harper Hall	1	1			1						3
49	Dorm 2 Katie Broun Hall	1	1			1						3
50	Dorm 3 Little Hall	1	1			1						3
51	Dorm 4 Teague Hall	1	1			1						3
52	Dorm 5 Dowdell Hall	1	1			1						3
53	Dorm 6 Glenn Hall	1	1			1						3
54	Dorm 7 Lane Hall	1	1			1						3
55	Dorm 8 Lupton Hall	1	1			1						3
56	Dorm 9 Keller Hall	1	1			1						3
57	Dorm 10 Owen Hall	1	1			1						3
58	Dorm J Boyd Hall				1	1						2
59	Dorm K Sasnett Hall	1	1		1	1						4
60	Dorm L		1			1						2
61	Dorm M		1			1						2
62	Aubie Hall	1	1					2				4
63	Eagle Hall	1	1					1				3
64	Magnolia Hall	2	1		1			6				10
65	Oak Hall	2	1					6				9
66	Plainsmen Hall	1	1					1				3
67	Talon Hall	1	1					1				3
68	Tiger Hall	1	1					1				3
69	Willow Hall	2	1					6				9
	<b>Total Systems</b>	<b>30</b>	<b>51</b>	<b>1</b>	<b>16</b>	<b>32</b>	<b>1</b>	<b>49</b>	<b>6</b>	<b>2</b>	<b>3</b>	<b>191</b>

**CRITICAL AREAS OF RESPONSIBILITY OF THE FIRE SAFETY PROGRAM**

<b>Fire Safety Education and Training Programs</b>	
Fraternity Fire Safety	2
Hands-on Fire Extinguisher Training	4
Fire Protection Systems	1
Consultations and Code Research	81
<b>Total</b>	<b>88</b>

<b>Fire and Life Safety Plan Reviews</b>	
Plan Reviews	35
<b>Total</b>	<b>35</b>

<b>New Construction Fire &amp; Life Safety Inspections</b>	
Construction Projects	10
Fire Alarm Acceptance Inspections/Test	15
Sprinkler System Acceptance Inspections/Test	14
Fire Pump Acceptance Inspections/Test	1
Above Ceiling Inspections	11
Fire Flow Hydrant Test	18

<b>Existing Building Fire and Life Safety Inspections</b>	
Dorm Buildings Inspected (100%)	31
Business/Assembly Buildings	34
Building Renovations Inspected	5
New Buildings Inspected	10
<b>Total</b>	<b>80</b>

<b>Fire Safety Permits issued</b>	
Hot Work Permit	18
Fire Watch Permit	14
Request to Disable Fire Protection	42
<b>Total</b>	<b>74</b>

<b>Inspection, Testing, and Maintenance of Water-based Fire Protection Systems and Extinguishers</b>	
Weekly Fire Pump Test	800
Monthly Sprinkler System Inspections	656
Quarterly Inspections/Test-Sprinkler Systems	345
Annual Sprinkler System Inspections/Test	82
Annual Fire Pump Test	16
Semi-Annual Special Hazard Systems	120
Monthly Fire Extinguisher Inspections	39446
Annual Fire Extinguisher Service	3595

<b>Special Events</b>	
Pre-game Stadium Inspections	8
Football Games	8
Graduation	1
<b>Total</b>	<b>9</b>

<b>City of Auburn Fire Division Response Information</b>			
<b>Responses by Month</b>		<b>Responses by Incident</b>	
January	19	Alarm Malfunctions	26
February	19	Activations/Unknown Cause	109
March	16	Cooking Alarms	54
April	19	Electrical Fires	2
May	15	Accidental Alarms	55
June	11	Smoke Odor	1
July	26	Smoking	2
August	35	Alarms Caused by Steam	22
September	35	Water flow Alarms	8
October	57	Fires Causing Damage	3
November	34	Malicious Mischief Activations	22
December	21	HazMat Incidents	0
		Dumpster Fires	2
		Natural Vegetation Fires	1
<b>Total</b>	<b>307</b>	<b>Total Responses</b>	<b>307</b>